


FEATURES & BENEFITS

OPTIONS

- ❑ Valve Repair Kit: Model VRK2AV, Model 5881 valve repair kit consisting of spring, disc, diaphragm, and renew seat.
- ❑ Valve Repair Kit: Model VRK3AV, valve repair kit-cover for 5881 valve.

For more information, visit www.hawsc.com or call (888) 640-4297.





SPECIFICATIONS

Model 5881 fountain valve is a push-button activated lead-free air valve used on all freeze-resistant drinking fountains. It is diaphragm controlled, supplied with an in-line mesh Y-strainer, and 1/2" IPS inlet and outlet.


APPLICATIONS

NOTE:

- 1 SCREWS & WASHERS
NOT SUPPLIED WITH COVERS.



PART NO. 0001980150 1

		1455 KLEPPE LANE SPARKS, NEVADA 89431 (775) 359-4712 FAX (755) 359-7424 E-MAIL: HAWS@HAWS.CO.COM WEBSITE: WWW.HAWS.CO.COM	
		ECN NO. REVISED PER BY: ECN: 4604 HM	MODEL(S)
DRAWN: D. OLLOM	DATE: 12/96	CHKD.:	5881
APPROVED:	DATE:	SCALE: 1:1	DRAWING TYPE: INSTALLATION
		SIZE: A	SHEET 1 OF 1
		DRAWING NO. 12856C00	REV 6