# \*\*\* OPTIONAL PCP WASHER FOR **FLUSH MOUNT** SURFACES (SEE NOTE BELOW)

## **5874PB** 1 4 5

**OO** 


PARTS BREAKDOWN

5874SS 1

VRK5874 1

VALVE REPAIR KIT

(STANDARD FLOW)



5874PBF 1

POLISH CHROME PLATED FLANGE PUSH BUTTON WITH VALVE FOR FLUSH MOUNT SURFACES ONLY.

PBA6



POLISHED CHROME PLATED FLANGED PUSH BUTTON FOR FLUSH MOUNT SURFACES ONLY.





#### 0006626653

WAVE WASHER FOR USE WITH BOTH RECESSED AND FLANGED STYLE PUSH BUTTON ASSEMBLIES. (MUST BE IN PLACE FOR PROPER **PUSH BUTTON OPERATION)** 



#### 0006983506

SPANNER WRENCH (ONLY INCLUDED WITH MODELS: 5874SS, 5874PB & 5874PBF)



#### 0003244389

THREADLOCKER TO SECURE PUSH BUTTON (ONLY INCLUDED W/PB SERIES)



POLISHED CHROME PLATED PUSH BUTTON WITH VALVE FOR BOTH RECESSED AND FLUSH MOUNT SURFACES. (ALSO USED FOR REPLACEMENT OF OLDER VALVE MODELS 5871, 5872, AND 5872HF - SEE NOTES 4 AND 5)



#### PBA7

POLISHED CHROME PLATED PUSH **BUTTON FOR BOTH RECESSED** AND FLUSH MOUNT SURFACES.



DO NOT REMOVE **GASKET WHICH COMES** WITH CARTRIDGE.

DO NOT REMOVE **GASKET WHICH COMES** WITH CARTRIDGE.

0001632151 2 3 5

VALVE CARTRIDGE (HIGH FLOW)

### **0002568123** 3 GASKET W/SCREEN

#### NOTES:

- MODELS 5874PB, 5874PBF, 5874SS, AND VRK5874 ARE EQUIPPED WITH A STANDARD FLOW CARTRIDGE. ORDER THESE MODELS WHEN REPLACING/REPAIRING VALVES WITH A STANDARD FLOW APPLICATION. DO NOT USE ON ANY MODELS THAT FEATURE A CUSPIDOR OR HAVE A HIGH FLOW APPLICATION WITHOUT IMPLEMENTING ADDITIONAL REQUIRED STEPS (SEE NOTES 2 AND 3).
- 2 MODELS 1025/G AND 3300/G EQUIPPED WITH A POP-UP BUBBLER HEAD (MODEL 5725) AND MODEL 2406 (EQUIPPED WITH A CUSPIDOR) ALL UTILIZE A HIGH FLOW CARTRIDGE TO ENSURE PROPER FLOW.
- 3 WHEN REPLACING A HIGH FLOW CARTRIDGE ASSEMBLY, DO NOT USE VRK5874. INSTEAD, USE THE FOLLOWING ITEMIZED COMPONENTS: HIGH FLOW CARTRIDGE (PN 0001632151), GASKET W/SCREEN (PN 0002568123) AND WAVE WASHER (PN 0006626653).

#### VALVE REPLACEMENT ON UNITS WITH OLDER 5871, 5872 (STANDARD FLOW) VALVES:

4 USE MODEL 5874PB AND TWO RING NUTS (SUPPLIED W/5874PB). USE ONE OR TWO OF THESE RING NUTS AS SPACERS TO MOVE THE NEW LONGER VALVE BODY FORWARD. THIS ALLOWS VALVE TO FIT IN TIGHT LOCATIONS FORMERLY OCCUPIED BY 5871 OR 5872 SERIES VALVES. NOTE: THESE RING NUTS MAY NOT ALWAYS BE NEEDED BUT ARE SUPPLIED IF REQUIRED.

### VALVE REPLACEMENT ON UNITS WITH OLDER 5872HF (HIGH FLOW) VALVES:

5 USE MODEL 5874PB, BUT, REPLACE THE STANDARD FLOW CARTRIDGE (SUPPLIED W/5874PB) WITH A HIGH FLOW CARTRIDGE (PN 0001632151), NOTE: FAILURE TO SWITCH CARTRIDGES WILL CREATE A LOW FLOW CONDITION. NOTE: USE ADDITIONAL RING NUTS IF NEEDED TO PROVIDE NECESSARY CLEARANCE FOR NEW LONGER VALVE BODY IN TIGHT LOCATIONS (SEE NOTE 4).



\*\*\* IF NEEDED, USE 1-3/4" O.D. X .050 THICK PCP WASHER PN 0006729529 (NOT SUPPLIED) IN SITUATIONS WHERE THE PUSH BUTTON HOLE IS SLIGHTLY OVERSIZED FOR THE 5874PB RING NUT.



MODEL(S)

1455 KLEPPE LANE SPARKS, NEVADA 89431 (775) 359-4712 FAX (755) 359-7424 F-MAIL HAWS@HAWSCO.COM

WEBSITE: WWW.HAWSCO.COM

0002077650

5874SS/5874PB/5874PBF/VRK5874/PBA6/PBA7 15873A00

WHEN ORDERING PARTS PLEASE SPECIFY MODEL NUMBER.

DRAWN DATE
H. MERRITT 04/09/09
APPROVED DATE